

Kyocera® F-1000/1010 Toner Unit



Oasis Imaging Products, Inc. Technical Support: (888) 627-6555

Reference Information:

OEM PN: 403065-03
OEM Yield: 10,000/set

Approximate Remanufacturing Time:

5 minutes

Instructions:

1. Open the upper unit and take out the old waste toner bottle.
2. Cap the old bottle, put it in a plastic bag, and throw away.
3. Install the new waste toner bottle without the cap.
4. Remove the old fuser cleaning pad by the yellow tab.
5. Place the new fuser cleaning pad in the fuser, pad side down and yellow tab toward you.
To prevent accidents, check that the new pad is positioned correctly and close the upper unit.
6. Insert new toner cartridge and pull seal.

Caution: The fuser unit and fuser cleaning pad may be hot. Whenever you replace the toner cartridge, also replace the waste toner bottle and fuser cleaning pad.

Printer Compatibility Information:

APRICOT LASER PRINTER	KYOCERA F-1200S	MANNESMANN TALLY 910
BRITISH TELECOM MP2010	KYOCERA F-2000A	MANNESMANN TALLY 910 SL
BROTHER LP 10	KYOCERA F-2010A	NCR 5037
CARLISLE SYST LASERGRAPH 10	KYOCERA FBP-01	NOKIA 1000
CARLISLE SYST LASERGRAPH 10A	KYOCERA P-2000 POSTSCRIPT	NOKIA 2020
DEREX INC DR 910	KYOCERA Q-8010A	ROHDE & SCHWARTZ
DEREX INC DRL 10	LEXI 1012	ROSETTA RT 1000M
DEREX INC DRL 10 PLUS	LEXI 1019	ROSETTA RT 2010M
DEVELOP 1000	LEXI 1019 II	STANDARD REGISTER PL 1000 MICR
DEVELOP 1100	LEXI 1087	STANDARD REGISTER PL 2000 MICR
DEVELOP 1200	LEXI 1087 II	STANDARD REGISTER PL 2002 MICR
HERMES LASER 1010	LEXI 2012	TRIUMPH ADLER SDR 7710
IMAGE TECHNOLOGIES MPS-1000 MICR	LEXI 2019	TRIUMPH ADLER SDR 7720
IMAGE TECHNOLOGIES MPS-2010 MICR	LEXI 2019 II	UNISYS MODEL 37
KLEINDIENST DR49	LEXI 2087	UNISYS 0478
KYOCERA F-1000A	LEXI 2087 II	UNIVAC MODEL 37
KYOCERA F-1010	MANNESMANN TALLY MT910	UNIVAC 0478
KYOCERA F-1200	MANNESMANN TALLY MT910 SL	ZYGAL KF-1010